

# Service Technical Information

MODEL NO. CSD-MD30 / MD50 / MD70 XR-MD100 / MD101 / MD200 / MD201 / H220MD
SUBJECT Precautions on Repairing MD Mechanisms



REF.No. :G - A0 - 036 - E1

DATE :28. JUN. 2000

Revision : SUBJECT change, model addition, MD mechanism suffix addition, and the addition of information

<CONTENTS>

The above models contain the "7ZG-9 B/B1" and "AZG-4 A" MD mechanism.  
Before repairing your product, confirm the type of MD mechanism is used in the product.

1. If your product contains the 7ZG-9 B/B1 mechanism, refer to the relevant Service Manual For the AZG-4 A mechanism, refer to Service Manual (09-001-341-2N2). Since the MD test mode is the same as that of the 7ZG-9, refer to the Service Manual corresponding to the model of your product. (The MD test mode described in the Service Manual of the AZG-4 A MD mechanism is for the XR-MD510.)
2. When activating the mechanisms EJECT mode, if the letter "A" can be seen through the hole in the holder shield top, the mechanism is a AZG-4 A. (See Fig-1 below) The "A" mark signifies the suffix assigned to AZG-4 A, and this mark is not given to the 7ZG-9 Series.

\*The 7ZG-9 B/B1 mechanism uses "RF325-74A" as its OWH. (See Fig-2 below)  
The AZG-4 A mechanism uses "RM-21E" as its OWH. (See Fig-3 below)



Fig-1 AZG-4 mechanism




Fig-2 OWH of the 7ZG-9 mechanism




Fig-3. OWH of the 7ZG-9 mechanism

<NOTE>

Although MD mechanisms have been changed, the main microcomputers remain unchanged. But, do not interchange the two mechanisms when loading because those two mechanisms are not compatible.

G	R	Code No.	Access Code	Modified Ser. No.	Parts Schedule
-	-	-	-	-	-