


2.7 Load Measurement 2: after replacement of DS02



2.8 Load Measurement 2: after replacement of IC501 5V LDO

