



Measured on Metrix MX 56 and test stand:

Switched output:						
	PIN	Name	500uA	5mA	50mA	500mA
Power inputs	2	IN1	H	H	H	H
	3	IN2	H	H	H	H
	4	IN3	H	H	H	H
Signal inputs / data	7	INS1	L	H	L	H
	6	INS2	L	L	H	H
	5	INS3	L	L	L	L
Power outputs	8	SW1	ON	OFF	OFF	OFF
	9	SW2	OFF	ON	OFF	OFF
	13	SW3	OFF	OFF	ON	OFF
	10	SW43	ON	ON	ON	ON
	11	SW42	ON	ON	ON	ON
	12	SW41	ON	ON	ON	ON

Wrong state, must be in OFF 1

Table 8-1. Function Table

IN2	IN1	COM TO NO, NO TO COM
L	L	OFF
L	H	COM = NO0
H	L	COM = NO1
H	H	COM = NO2

TS5A3359

Cislo vykresu /drawing number/: 018-53ARC1_V2.SchDoc		
Kreslil /drawn by/: Juraj Michalek	Kontroloval /checked by/: Jack Daniel	Projekt/project/: 018
Schválil /approved by/: Pyotr Smirnov	Podpis/signature/:	Nazov listu/sheet name/: ARC1_V2.SchDoc
Datum/date/: 02.03.2024		List/Sheet/: 1 / 2

